

PAINTCOR

SUPREME QUALITY *Since 1986*

TUTORIAL 17:

PAINTING OVER WALL TILES

Determining your product requirement:

- Measure the surface area you wish to paint.
- Determine which products are needed for the surface you wish to paint and the finish you wish to achieve.
- Check the Theoretical Spread Rates (TSR) on each of the specified products and see how many coats of each are recommended, then calculate what quantities of each product you will require, remembering to make adjustments for the porosity for each surface. TSRs are based on products applied to smooth, sealed surfaces. (E.g. an unsealed scratch plaster surface will absorb more paint than a sealed smooth one, so allow for a lower spread rate on porous surfaces).
- Check out the specifications on all the top coat choices (referring to the relevant data sheets) and decide which is right for you.

PAINTING OVER WALL TILES

TILES OTHER THAN SHOWER TILES

Surface Preparation

1. Wash tiles down with soap and water. Allow to dry.
2. Wipe grouting and tiles down with undiluted household bleach (to kill algae). Allow to dry. Remove dead algae by dry-brushing if necessary.
3. Finally wipe tiles down with lacquer thinners to ensure thorough cleaning of tiles.

Application Method

1. Apply 1 coat Paintcor **GlazeTilePrimer** to clean dry tiles. Allow to dry. Apply by brush or roller to an even consistency.
Take care not to apply the product too thick. Cover the surface to which it is being applied evenly.
2. Apply 1 or 2 top coats of **EnviroCoat**, **Elegance**, **EnduraCoat** in desired colour.
3. Allow this system at least 24 hours to dry before subjecting to excessive humid or wet conditions.

Note: Do not attempt to spread **GTP** too far as this will give a poor streaky finish

Relevant Product Information

Glazed Tile Primer (GTP)	
Theoretical Spread Rate	10m ² per litre
No. of Coats required	1 Coat on clean dry tiles
Application Method	Brush, Roller or Spray
Drying Time	@ 25°C – 60 minutes

Paintcor cc

Reg No: CK 86/19456/23
VAT No: 4830119311

Members: G. Williams, G. Adendorff
W. Williams

Head office: 1494 Mailship
street, Laser Park, Honeydew, 2040
Postal Address: P.O. Box 917,
Northriding, 2162
RSA

Email
sale@paintcor.co.za
Website
www.paintcor.co.za

Tel: 011 794 2885
Fax no: 011 794 6955
Emergency Numbers
+27(0) 79 526 1565
+27(0) 84 305 5636



SABS
ISO 9001 Accredited



PAINTCOR

SUPREME QUALITY *Since 1986*

EnduraCoat	
Theoretical Spread Rate	10m ² per litre
No. of Coats required	1 Coat
Application Method	Brush, Roller or Spray
Drying Time	@ 25°C – 3 hours to Touch Dry @ 25°C – 6 hours Overcoating

EnviroCoat	
Theoretical Spread Rate	10m ² per litre
No. of Coats required	2 Coats
Application Method	Brush, Roller or Spray
Drying Time	@ 25°C – 60 minutes

Elegance (Matt or Silk)	
Theoretical Spread Rate	10m ² per litre
No. of Coats required	2 Coats minimum
Application Method	Brush, Roller or Spray
Drying Time	@ 25°C – 60 minutes

Paintcor cc
Reg No: CK 86/19456/23
VAT No: 4830119311

Members: G. Williams, G. Adendorff
W. Williams

Head office: 1494 Mailship
street, Laser Park, Honeydew, 2040
Postal Address: P.O. Box 917,
Northding, 2162
RSA

Email
sale@paintcor.co.za
Website
www.paintcor.co.za

Tel: 011 794 2885
Fax no: 011 794 6955
Emergency Numbers
+27(0) 79 526 1565
+27(0) 84 305 5636



SABS
ISO 9001 Accredited

